WELL COMPLETION REPORT 3/71

PA 23

LAVE CARNEL

PUTNAM COUNTY DEPARTMENT OF HEALTH

Division of Environmental Health Services COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

		REPO	ORT MUST	BE SI	UBMITTED	WITHIN	30 DA	YS OF WE	LL COMPLE	TION	1105	
OWNER	Cha	rle:	s Mo	10/40	atian	ADDRESS	A	CHR	rson			
LOCATION OF WELL	Tho		(NO. 6.	H: 1	Rel		,	(Town)	1301		(Lot Number)	
PROPOSED USE OF WELL	DOMES DOMES			HESS SLISHMEN	-	FAR	M	ING	TEST WEI	, 322	Н	
DRILLING EQUIPMENT	ROTAR	Y		PRESSED ERCUSSIO	on.	CAB			OTHER (Specify)			
CASING LENGTH (leet)		55	DIAMETER (Inches) WEIGHT P		L9			WELDED	PRIVE SHOE WAS CASING GROUTEDY YES NO		SING GROUTED!	
YIELD TEST	BAILED		PUMP	ED [COMPRES	SED AIR	1	HOURS &	G.F.M. 15	YIELD (G.		
WATER LEVEL	MEASURE F	URE FROM LAND SURFACE - STATIC (Specify			city feet) DURIN	V (cot) DURING YIELD TEST (rout)			Depth of Camp	Depth of Completed Well in feet below Land surface: 745		
SCREEN	MAKE									LENGTH C	PEN TO AQUIFER (feet)	
DETAILS	SLOT SIZE		DIAMETER (nches)	IF GRAVEL PACKED:		er of we pack (In	Il including ches):	GRAVEL SIZE (Inc	thes) FROM (tes	t) TO (feet)	
PEET to FEET		FORMATION DESCRIPTION					Sketch exact location of well with distances, to at least two permanent landmarks.					
If yield w		different	depths during		list below ER MINUTE							
DATE WELL COMPLE	7ED D.	ATE OF	REPORT - 84	WELL C	DRILLER (SK	gnature)	Œ	Eller	74,	all		